

General Environmental Incident Summary

Incident: 4059 **Date/Time Notice:** 4/4/2016 **DEM Incident No:**
Responsible Party: Goodrich Corporation
Date Incident: 4/4/2016 **Time Incident:** 0500 **Duration:** 2 hours
County: Stutsman **Twp:** 140 **Rng:** 63 **Sec:** 19 **Qtr:** NW
Lat: 46.00000 **Long:** -98.00000 **Method:** Derived from Twn Rng
Location Description: "Goodrich Corporation, acting by and through its Interiors business unit, Goodrich Cargo Systems, a UTC Aerospace Systems Company"
2604 Highway 20 North
Jamestown, ND 58401
Submitted By: Jill Mazur **Affiliation:** Site EHS Supervisor
Address: 2604 Highway 20 North
City: Jamestown **State:** ND **Zip:** 58476

Received By:

Contact Person: Brent Harris
2604 Highway 20 North
Jamestown, ND 58401

Distance Nearest Occupied Building: 1000 Feet **Release Contained:** Yes

Type of Incident: Pump Leak

Description of Released Contaminant: Sulfuric Acid Solution (13% sulfuric acid and 87% water)

Volume Spilled: 396.00 pounds **Ag Related:** No

EPA Extremely Hazardous Substance: Yes **Reported to NRC:** Unknown

Cause of Incident:

The pump on the sulfuric tank failed causing the spill. The spill released into the process line mechanical room building D at first then traveled under the South wall of the building out into the parking lot. The spill within the parking lot is approximately 100 feet long and 2 feet wide. The chemical did not come in contact with the storm water drain therefor did not reach the onsite detention pond nor the city municipality storm water drainage system.

Risk Evaluation:

No immediate risk

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil was impacted from the spill. Initial cleanup was completed. Impacted soil is being removed for proper disposal by a 3rd party, Clean Harbors.

Action Taken or Planned:

The pump to the tank was shutoff immediately and floor dry was placed on spill at 6:45AM. Awareness cones were placed on both sides of the spill to detour vehicle and foot traffic. Soil was impacted from the spill. Initial cleanup was completed. Impacted soil is being removed for proper disposal by a 3rd party, Clean Harbors.

Wastes Disposal Location: UTC Aerospace Systems has engaged Clean Harbors to dispose of the hazardous waste.

Agencies Involved: Local Fire Department, Jamestown Waste water Treatment facility

Updates

Date: 4/4/2016 **Status:** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Spoke to contact person. Based on our conversation, company responded quickly and adequately to remediate release from the surface and soils that were impacted. No further follow-up required.